# **Changing style of hidden lines**

On a monitor the hidden lines on the drawings created in Pro/ENGINEER WildFire 2.0 are shown as grey thin lines.



This is what we see in WildFire 2.0 and what we have always to remember about:



Question: *How the printout will look like*?

It may be the same *grey thin line*:



#### Grey thin line:



But it may be also grey short-dash line:



#### In fact these are two dash lines!

- $\succ$  The first one has the dashes of 0.1 mm length the line looks like the solid line,
- $\succ$  the second is 1 mm and becomes visible.

If you see on the drawing printout a thin solid grey hidden line – just change the setting for the hidden line plotting!

To change the settings: Open in the main menu Tools – Options



## and you will see the *Options* window with the list of possible setting.



Find here the option *plot\_linestyle-scale* and check its value.

Change the value to the bigger one, for example to 3 mm.

A 9	RGONXAAAM	an 🖂 - 🗌 🔽	3-0 9	হ্ হ হ	l df. 🤿 📗	a a a	0 4
	🖳 Options					×	
L.⇒	Showing:			Sort:			
	Current Session	🗔 🔁	<b>1</b>	Alphabetical		•	
- -	Show only options loaded from file						
<u> </u>							
		Value	Status	Source			
	🥪 💋 piping_schematic_driven	no *	ě.				
	🚽 🚽 piping_schematic_xml_dir	C:\Documents and S.	🎽 👘				
	,	C:\Program Files\pro.	🎽 👘				
+		MNEMONIC *	¥.				
	🥖 🚽 piping_thumb_wheel_increment	1.000000 ×	¥.				
	🥖 🚽 piping_thumb_wheel_ratio_inc	0.010000 ×	¥.				
	─────────────────────────────────────	manual *	ě.				
		1.000000 ×	۲	session			
	✓ plot_proceed_dialog	no *	ě.				
		no *	¥.				
	prev_proc_comp_def_color	0.000000 0.000000	· 🎽				
	ypro_font_dir	C:\Program Files\pro	🎽				
	🚽 🚧 pro_gplug_dir	C:\Program Files\pro.	🎽 👘				
	🖉 🚽 🖉 pro_note_dir	C:\Documents and S.	🎽 👘				
	₩ pro_palette_dir	C:\Program Files\pro.	🎽 👘				
	🖉 🚧 pro_spool_dir	C:\Documents and S.	🆌 👘				
	🚽 🚧 pro_surface_finish_dir	C:\Program Files\pro.	🎽 👘				
	🚽 🚽 pro_symbol_dir	C:\Documents and S.	🎽			-	
	Option:	<u>V</u> alue:					
	plot_linestyle_scale	3.000000			<ul> <li>Ac</li> </ul>	id / Change	
	Q Find	Browse				DAdd or upda	te selected option
					ОК Арр	y Close	

Click "Add/Change" button.

### New value of *plot\_linestyle-scale* option will appear in the corresponding line:

	<u>8</u> \$* #Ma (573 → 11 1	🔊 🥍 🎋	ଧ୍ୟ୍ର୍ର		
Options				2	<u>ย</u>
Showing:		Se Se	ort:		
Current Session	<b>T</b>	) 🗊 🔽	Alphabetical	•	
Show only options loaded from file					
	Value	Status	Source		
	MNEMONIC *	ĭ		▲	
	1.000000 ×	ĭ			
🦷 🚧 piping_thumb_wheel_ratio_inc	0.010000 ×	ř.			
🚽 🛶 💋 piping_wildfire_convert	manual *	ĭ			
<mark></mark>	3.000000	*	session		
plot_proceed_dialog	no *	ĭ			
	no *	¥.			
prev_proc_comp_def_color	0.000000 0.00000	)0 🏅			
🚽 🚽 pro_font_dir	C:\Program Files\p	pro 🏅			
y pro_gplug_dir	C:\Program Files\p	pro 🏅			
🚽 🚽 pro_note_dir	C:\Documents and	d S 🏅		_	
─── <del>ダ</del> pro_palette_dir	C:\Program Files\p	oro 🏅			
y pro_spool_dir	C:\Documents and	d S 🏅			
🌮 pro_surface_finish_dir	C:\Program Files\p	oro 🏅			
🚽 🚽 pro_symbol_dir	C:\Documents and	d S 🏅			
pro_unit_length	unit_inch *	ĭ			
pro_unit_mass	unit_pound *	ĭ			
💋 profile_output_utils	no *	¥.		-	
Ī				F	
Option:	⊻alue:				
				<ul> <li>Add / Change</li> </ul>	]
Q Find	Browse			Delete	
				OK Apply Close	
				Save and app	ly file cha

Now the dashes on the printout became big and clearly visible:



The printed image will finally look:



